


For Gold and Silver



Gypsum-based recommended investment Yoshino Gypsum Highstone C-5, R&R SV20, Ultrabest

- ※ The burn out pattern in the blue squares must be followed closely: 3 hours at 150° C, 1.5 hours at 400° C, and 1 hour at 450° C, Otherwise, the temperature control you are currently using is fine.
- ※ Adjust the mooring time at 400° C by about 20° C up or down in 10° C increments, depending on the individual variability of the electric furnace, according to the roughness of the plaster